


**Tilcon New Jersey
Pompton Lakes Quarry
Quarterly Blast Compliance Summary
2nd Quarter 2018**

Date	Time	Recording Location	Within NJ Ground Vibration Limits*	Within NJ Air Overpressure Limits**
4/2/2018	15:00	211 Hamburg Turnpike	Yes	Yes
4/2/2018	15:00	Cablevision Tower	Yes	Yes
4/2/2018	15:00	Bloomingtondale DPW Yard	Yes	Yes
4/9/2018	13:00	211 Hamburg Turnpike	Yes	Yes
4/9/2018	13:00	Cablevision Tower	Yes	Yes
4/9/2018	13:00	Bloomingtondale DPW Yard	Yes	Yes
4/10/2018	12:59	211 Hamburg Turnpike	Yes	Yes
4/10/2018	12:59	Cablevision Tower	Yes	Yes
4/10/2018	12:59	Bloomingtondale DPW Yard	Yes	Yes
4/11/2018	11:30	211 Hamburg Turnpike	Yes	Yes
4/11/2018	11:30	Cablevision Tower	Yes	Yes
4/11/2018	11:30	Bloomingtondale DPW Yard	Yes	Yes
4/17/2018	13:00	211 Hamburg Turnpike	Yes	Yes
4/17/2018	13:00	Cablevision Tower	Yes	Yes
4/17/2018	13:00	Bloomingtondale DPW Yard	Yes	Yes
4/19/2018	13:30	211 Hamburg Turnpike	Yes	Yes
4/19/2018	13:30	Cablevision Tower	Yes	Yes
4/19/2018	13:30	Bloomingtondale DPW Yard	Yes	Yes
4/23/2018	12:00	211 Hamburg Turnpike	Yes	Yes
4/23/2018	12:00	Cablevision Tower	Yes	Yes
4/23/2018	12:00	Bloomingtondale DPW Yard	Yes	Yes
4/30/2018	13:15	211 Hamburg Turnpike	Yes	Yes
4/30/2018	13:15	Cablevision Tower	Yes	Yes
4/30/2018	13:15	Bloomingtondale DPW Yard	Yes	Yes
5/2/2018	12:30	211 Hamburg Turnpike	Yes	Yes
5/2/2018	12:30	Cablevision Tower	Yes	Yes
5/2/2018	12:30	Bloomingtondale DPW Yard	Yes	Yes
5/8/2018	12:30	211 Hamburg Turnpike	Yes	Yes
5/8/2018	12:30	Cablevision Tower	Yes	Yes
5/8/2018	12:30	Bloomingtondale DPW Yard	Yes	Yes
5/16/2018	12:00	211 Hamburg Turnpike	Yes	Yes
5/16/2018	12:00	Cablevision Tower	Yes	Yes
5/16/2018	12:00	Bloomingtondale DPW Yard	Yes	Yes
5/18/2018	11:00	211 Hamburg Turnpike	Yes	Yes
5/18/2018	11:00	Cablevision Tower	Yes	Yes
5/18/2018	11:00	Bloomingtondale DPW Yard	Yes	Yes

Date	Time	Recording Location	Within NJ Ground Vibration Limits*	Within NJ Air Overpressure Limits**
5/22/2018	11:30	211 Hamburg Turnpike	Yes	Yes
5/22/2018	11:30	Cablevision Tower	Yes	Yes
5/22/2018	11:30	Bloomingtondale DPW Yard	Yes	Yes
5/30/2018	13:00	211 Hamburg Turnpike	Yes	Yes
5/30/2018	13:00	Cablevision Tower	Yes	Yes
5/30/2018	13:00	Bloomingtondale DPW Yard	Yes	Yes
6/1/2018	11:30	211 Hamburg Turnpike	Yes	Yes
6/1/2018	11:30	Cablevision Tower	Yes	Yes
6/1/2018	11:30	Bloomingtondale DPW Yard	Yes	Yes
6/4/2018	11:00	211 Hamburg Turnpike	Yes	Yes
6/4/2018	11:00	Cablevision Tower	Yes	Yes
6/4/2018	11:00	Bloomingtondale DPW Yard	Yes	Yes
6/7/2018	12:00	211 Hamburg Turnpike	Yes	Yes
6/7/2018	12:00	Cablevision Tower	Yes	Yes
6/7/2018	12:00	Bloomingtondale DPW Yard	Yes	Yes
6/12/2018	10:00	211 Hamburg Turnpike	Yes	Yes
6/12/2018	10:00	Cablevision Tower	Yes	Yes
6/12/2018	10:00	Bloomingtondale DPW Yard	Yes	Yes
6/14/2018	10:59	211 Hamburg Turnpike	Yes	Yes
6/14/2018	10:59	Cablevision Tower	Yes	Yes
6/14/2018	10:59	Bloomingtondale DPW Yard	Yes	Yes
6/15/2018	12:59	211 Hamburg Turnpike	Yes	Yes
6/15/2018	12:59	Cablevision Tower	Yes	Yes
6/15/2018	12:59	Bloomingtondale DPW Yard	Yes	Yes
6/20/2018	11:00	211 Hamburg Turnpike	Yes	Yes
6/20/2018	11:00	Cablevision Tower	Yes	Yes
6/20/2018	11:00	Bloomingtondale DPW Yard	Yes	Yes
6/22/2018	11:00	211 Hamburg Turnpike	Yes	Yes
6/22/2018	11:00	Cablevision Tower	Yes	Yes
6/22/2018	11:00	Bloomingtondale DPW Yard	Yes	Yes
6/29/2018	11:30	211 Hamburg Turnpike	Yes	Yes
6/29/2018	11:30	Cablevision Tower	Yes	Yes
6/29/2018	11:30	Bloomingtondale DPW Yard	Yes	Yes


*State of New Jersey Administrative Code Title 12:190; Subchapter 7.26
**State of New Jersey Administrative Code Title 12:190; Subchapter 7.25

Comparison of Measured Blast Vibrations to Current U.S. Bureau of Mines Recommendations Tilcon New Jersey Pompton Lakes Quarry 2nd Quarter 2018



*As per State of New Jersey Administrative Code Title 12:190; Subchapter 7.26

Air Overpressure Levels from Tilcon New Jersey - Pompton Lakes Quarry 2nd Quarter 2018



*As per State of New Jersey Administrative Code Title 12.190; Subchapter 7.25

■ 211 Hamburg Turnpike
 ■ Cablevision Tower
 ■ Bloomingdale DPW Yard